FIG.1(a)





FIG.1(b)









FIG.3



PLATING TANK CAPACITY / DROSS REMOVING TANK CAPACITY

( W1/W2 )

FIG. 4




FIG.5





FIG.6



af giving giving giving given between steeling giving and the second given giving givi

FIG.7




FIG.8





FIG.9



### FIG.10(a)




FIG.10(b)




FIG.11






FIG. 12





### FIG.15(a)




FIG.15(b)




FIG. 16




FIG.17(a)




FIG.17(b)




FIG.17(c)




FIG. 18




FIG. 19





FIG.20



# FIG.21(a)




FIG.21(b)




FIG.21(c)





FIG.22



### FIG.23(a)




FIG.23(b)






FIG.23(c)



### FIG.24(a)



# FIG.24(b)




FIG. 24(c)




FIG. 25




FIG. 26




FIG. 27




FIG.28




FIG.29




FIG.30




FIG.31




FIG.32




FIG.33




FIG.34(a)





FIG. 35






FIG.37






FIG. 38





IG. 35

FIG.40




FIG.41




FIG.42




FIG.43





FIG.44(a)



# FIG.44(b)




FIG. 44(c)




FIG.45




FIG. 46




FIG. 47




FIG. 48(a)

